

Triumph

	Thunderbird		81-	MCB 99						
	TSS Electro 8 Va		84-	MCB 533						
	TSX		82-83	MCB 99					MCB 99	
	600 Daytona	806LW	03-04	MCB 595	*	SV	SRQ	CRQ	MCB 585 LF	SH
	600 Speed Four	806LB	03-	MCB 595	*	SV	SRQ	CRQ	MCB 585 LF	SH
TT	600	806AD	00-03	MCB 595	*	SV	SRQ	CRQ	MCB 585 LF	SH
	650 Daytona	865LX	05-	MCB 595	*	SV	SRQ	CRQ	MCB 585 LF	SH
	675 Daytona	D67LC	06-08	MCB 737 SV	*	SRQ	CRQ		MCB 585 LF	SH
	675 Daytona Triple		09-	MCB 816 SV	*	SRQ	CRQ		MCB 585 LF	SH
	675 Street Triple	D67LD	08	MCB 598 SV	*	SRQ			MCB 585 LF	SH
	675 Street Triple R		09-	MCB 737 SV	*	SRQ	CRQ		MCB 585 LF	SH
	750 Bonneville 750		84-	MCB 533						
	750 Bonneville T140V		75-81	MCB 99					MCB 99	
	750 Bonneville T140V		81-83	MCB 99	*				MCB 99	
	750 Bonneville U.K.		87-	MCB 19	*				MCB 19 LF	
	750 Daytona	330BEM	91-	MCB 595	*	SV	SRQ	CRQ	MCB 604 LF	
	750 Trident	←	T300C	91-		SV			MCB 604 LF	
	750 Trident	→	T300C	91-		SV				
	750 TSS		82-83	MCB 99					MCB 99	





→ TRIUMPH

800	Bonneville	908MD	01-	MCB 598	SV			MCB 582	SH
800	Speedmaster	986ML	03-05	MCB 598	* SV	SRQ		MCB 582	SH
800	America		02-	MCB 598	SV			MCB 582	SH
800	Scrambler	986MG	06-	MCB 598	SV			MCB 582	SH
865	America		07-	MCB 598	SV			MCB 582	SH
865	Speedmaster	986ML	05-	MCB 598	SV			MCB 582	SH
900	Bonneville	986MF	05-08	MCB 598	SV			MCB 615	SH
900	Bonneville	986MF	09-	MCB 598	SV			MCB 582	SH
900	Daytona	T300	91-	MCB 595 SV	* SRQ	CRQ		MCB 604 LF	
900	Daytona Super III	T300B	94-	MCB 656 SV	* SRQ			MCB 604 LF	
900	Legend TT		99-01	MCB 598 SV	SRQ			MCB 599 LF	SH
900	Speed Triple	T300B	94-95	MCB 595 SV	* SRQ	CRQ		MCB 615	SH
900	Speed Triple	T509	96-00	MCB 595 SV	* SRQ	CRQ		MCB 582	SH
900	Sprint	← T300	91-93	MCB 582	SV			MCB 604 LF	
900	Sprint	→ T300	91-93	MCB 615	SV				
900	Sprint		94-00	MCB 595	* SV	SRQ		MCB 604 LF	
900	Thrupton	986ME	04-	MCB 598	SV			MCB 582	SH
900	Thunderbird, Sport		95-	MCB 598	SV	SRQ		MCB 599 LF	SH
900	Tiger	← T400	93-98	MCB 582	* SV			MCB 604 LF	
900	Tiger	→ T400	93-98	MCB 615	* SV				
900	Tiger	T709	99-01	MCB 598	* SV			MCB 599 LF	SH
900	Trident	← T300	91-	MCB 582	SV			MCB 604 LF	
900	Trident	→ T300	91-	MCB 615	SV				
900	Trophy	← 336DDM	91-92	MCB 582	SV			MCB 615	SH
900	Trophy	→ 336DDM	91-92	MCB 615	SV				
900	Trophy		93-01	MCB 595	* SV	SRQ	CRQ	MCB 615	SH
955	Daytona	T595	96-	MCB 595	* SV	SRQ	CRQ	MCB 582	SH
955	Daytona i	595N	99-	MCB 595	* SV	SRQ	CRQ	MCB 582	SH
955	Speed Triple	595N	99-	MCB 595	* SV	SRQ	CRQ	MCB 582	SH
955	Sprint RS	T695	99-02	MCB 595	* SV	SRQ		MCB 604 LF	
955	Sprint RS	695AC	03-	MCB 595	* SV	SRQ		MCB 582	SH
955	Sprint ST	T695	99-	MCB 595	* SV	SRQ		MCB 582	SH
955	Tiger i		01-04	MCB 598	* SV			MCB 599 LF	SH
955	Tiger i		05-	MCB 598	* SV			MCB 604 LF	
1000	Daytona Sport	344HDM	91-	MCB 595	* SV	SRQ	CRQ	MCB 604 LF	
1050	Speed Triple	515NJ	05-07	MCB 737 SV	* SRQ	CRQ		MCB 582	SH
1050	Speed Triple	4 ☐ 515NJ	08-	MCB 721SV	* SRQ	CRQ		MCB 582	SH
1050	Sprint ST	215NA	05-	MCB 595	* SV	SRQ	CRQ	MCB 582	SH
1050	Sprint ST (ABS)	4 ☐ 215NA	08-	MCB 721SV	* SV			MCB 582	SH
1050	Tiger	115NG	07-	MCB 737 SV	* SV			MCB 615	SH
1200	Daytona	T300	93-	MCB 595	* SV	SRQ	CRQ	MCB 604 LF	
1200	Trophy	← 342CSM	91-92	MCB 582	SV			MCB 604 LF	
1200	Trophy	→ 342CSM	91-92	MCB 615	SV				
1200	Trophy	342CSM	93-	MCB 595	* SV	SRQ		MCB 604 LF	
1600	Thunderbird		09-	MCB 595	* SV			MCB 671	SH
2300	Rocket III	C23XB	04-	MCB 595	* SV			MCB 671	SH
2300	Rocket III Touring		08-	MCB 595	* SV			MCB 671	SH