

# Peugeot

	50	Blaster		09-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>				
	50	Buxy	AJP	94-	<b>MCB 535</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Buxy	Brembo FE 053 DE	94-	<b>MCB 696</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Buxy	Hentong	94-	<b>MCB 522</b>					<b>MCS 800</b>	
	50	Elyseo	AJP G1A	98-01	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Elyseo	GA1	02-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Elystar	G1A	03-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 735</b>	<b>LF</b>
	50	Jet-Force		03-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Looxor/TSDI	B1	01-05	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Looxor		06-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Ludix Blaster		04-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Ludix One/Classic		04-	<b>MCS 800</b>					<b>MCS 800</b>	
	50	Ludix Snake/Trend/Eleganc		04-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Speedake	AJP	94-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Speedake	Brembo FE 053 DE	94-	<b>MCB 696</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Speedake	Hentong	94-	<b>MCB 522</b>					<b>MCS 800</b>	
	50	Speedfight 2 AC	S1B	01-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Speedfight 2 LC	S1B	01-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Speedfight 2 X-Race	S1B	03-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Speedfight AC	AJP S1BDE	96-00	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Speedfight LBD/LBDP	S1BDE	00-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Speedfight LC	AJP S1BDE	96-00	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	50	Speedfight LC	Brembo S1BDE	96-00	<b>MCB 674</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Squab	AJP	94-98	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	
	50	Squab	Hentong	94-98	<b>MCB 522</b>					<b>MCS 800</b>	
	50	Trekker Metal-X	S1A	01-	<b>MCB 535</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Trekker Offroad	S1ADE	99-	<b>MCB 522</b>					<b>MCS 800</b>	
	50	Trekker Road	S1ADE	99-	<b>MCB 535</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Trekker Streetboard	S1A	00-	<b>MCB 535</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Trekker Urban Black	S1A	00-	<b>MCB 535</b>	<b>SR</b>				<b>MCS 800</b>	
	50	V-Clic		08-	<b>MCB 590</b>					<b>MCS 800</b>	
	50	Vivacity	AJP S1C	99-	<b>MCB 535</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Vivacity	Hentong	05-	<b>MCB 522</b>					<b>MCS 800</b>	
	50	Zenith Luxe LM		94-	<b>MCB 696</b>	<b>SR</b>				<b>MCS 800</b>	
	50	Zenith M, MA		94-	<b>MCS 813</b>					<b>MCS 800</b>	
SV	50	Geo, L	F 052-DE	93-	<b>MCB 650</b>					<b>MCB 575 LF</b>	
SV	50	J, Junior	F 052-DE	93-	<b>MCS 800</b>					<b>MCS 800</b>	
TKR	50	S/Furios, WRC	S1B	03-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
XP 6	50	Trail, Enduro		02-	<b>MCB 535</b>	<b>RQ</b>				<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
XPS- 6	50	Supermotard		04-	<b>MCB 734</b>	<b>SR</b>				<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
XR 6	50	Race Spec		02-07	<b>MCB 629</b>					<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
XR 7	50			08-	<b>MCB 780 SV</b>					<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	80	Metropolis			<b>MCS 800</b>					<b>MCS 813</b>	
SV	80		F 082-DE	91-92	<b>MCB 650</b>					<b>MCS 800</b>	
SV	80		F 082-DE	93-	<b>MCB 665</b>					<b>MCS 800</b>	
	100	Elyseo	G2A	02-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCB 535</b>	<b>SR</b> <b>RQ</b>
	100	Elyseo	AJP G2A	98-01	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>			<b>MCS 800</b>	





→ **PEUGEOT**

	100	Looxor		B1A	01-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>		<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>
	100	Speedfight	AJP	S2A	00-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>		<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>
	100	Speedfight 2, X-Race		S2A	01-	<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>		<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>
	100	Trekker Road		S2A	99-	<b>MCB 535</b>	<b>SR</b>			<b>MCS 800</b>		
	100	Vivacity	AJP	S2A	99-	<b>MCB 535</b>	<b>SR</b>			<b>MCS 800</b>		
	100	Vivacity	Hentong		05-	<b>MCB 522</b>						
	125	Elyseo		G2A	00-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	125	Elyseo	AJP	G2A	98-99	<b>MCB 535</b>	<b>SR</b>			<b>MCS 831</b>		
	125	Elystar		H2	03-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	125	Jet-Force Compressor			03-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	125	Looxor		P2	03-	<b>MCB 726</b>	<b>SV</b>			<b>MCB 535</b>		
	125	Ludix			04-	<b>MCB 535</b>	<b>SR</b>			<b>MCS 800</b>		
	125	Satelis			04-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	125	Satelis ABS			04-	<b>MCB 736</b>	<b>SV</b>			<b>MCB 735 LF</b>		
SV	125			F121	91-92	<b>MCB 650</b>				<b>MCS 800</b>		
SV	125	C Executive		F121	96-	<b>MCB 665</b>				<b>MCS 800</b>		
	125	Geopolis Premium			06-	<b>MCB 744</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	150	Elyseo		G2A	00-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	150	Elystar		H2	03-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	150	Looxor			03-	<b>MCB 726</b>				<b>MCB 535</b>	<b>SR</b>	<b>RQ</b>
	250	Geopolis Premium	Nissin		06-	<b>MCB 744</b>	<b>SR</b>			<b>MCB 744</b>	<b>SR</b>	
	250	Geopolis ABS			06-	<b>MCB 736</b>	<b>SV</b>			<b>MCB 735 LF</b>		
	250	Satelis ABS			06-	<b>MCB 736</b>	<b>SV</b>			<b>MCB 735 LF</b>		
	250	Satelis Premium			06-	<b>MCB 744</b>	<b>SR</b>			<b>MCB 689</b>		
	400	Geopolis, ABS	Nissin		07-	<b>MCB 744</b>	<b>SR</b>			<b>MCB 744</b>	<b>SR</b>	
	400	Geopolis	AJP		07-	<b>MCB 734</b>	<b>SR</b>			<b>MCB 735 LF</b>		
	400	Satelis ABS			06-	<b>MCB 736</b>	<b>SV</b>			<b>MCB 735 LF</b>		
	400	Satelis Premium			06-	<b>MCB 598</b>	<b>SV</b>			<b>MCB 689</b>		
	500	Geopolis			09-	<b>MCB 598</b>	<b>SV</b>			<b>MCB 744</b>	<b>SR</b>	
	500	Satelis ABS			04-	<b>MCB 736</b>	<b>SV</b>			<b>MCB 735 LF</b>		
	500	Satelis Premium			04-	<b>MCB 598</b>	<b>SV</b>			<b>MCB 689</b>		