


Honda

CB	50	J	CB50J	81-83	MCB 504					MCS 804
CB	50	J	CB50J	-80	MCS 804					MCS 804
CY	50		CY50	80-83	MCS 800					MCS 800
MB	50	S	AC01	80-	MCB 510	SI				MCS 804
MBX	50	SD	AC05	83-	MCB 525					MCS 804
MT	50	S	AD01	80-	MCS 804					MCS 804
MTX	50	S	AD04	83-	MCS 804					MCS 804
NB	50	M (Aero)	AB07	84-	MCS 827					MCS 813
NCZ	50		AB12	81	MCS 827					MCS 827
NH	50	Lead	AF01	94-	MCB 665					MCS 813
NH	50	Lead	AF01	86-93	MCS 800					MCS 813
NH	50	Lead (Trommelbr.)	AF01	94-	MCS 800					MCS 813
NPS	50	Zoomer		01-	MCS 825					MCS 825
NS-1	50			91-	MCB 525					
NSR	50			93-	MCB 615	SV				MCS 804
NSR	50	(Japan)		93-	MCB 525					MCB 575 LF
NSR	50	S	AC08	89-92	MCB 525					MCS 804
PA	50	STD		86-	MCS 828					MCS 828
PK	50	DX Wallaroo	AB25	90-	MCS 825					MCS 800
PX	50	MS	AB06S	84-	MCS 828					
QR	50			93-	MCS 827					MCS 825
SA	50	Vision	AF29	88-94	MCS 825					MCS 825
SA	50	Vision	AF29	85-87	MCS 827					
SFX	50	Sport	AF37	96-	MCB 674	SR	RQ			MCS 800
SGX	50	sky	AF43	97-	MCB 674	SR	RQ			MCS 800
SGX	50	sky DX	AF43	00-	MCB 674	SR	RQ			MCS 800
SH	50	Fifty	AF40	00-	MCB 674	SR	RQ			MCS 800
SH	50	Scoopy	AF40	96-	MCB 674	SR	RQ			MCS 800
SJ	50	Bali	AF32	93-99	MCB 673					MCS 800
SRX	50	Shadow	AF42	98-	MCB 575 SR					MCS 800
ST	50		AB23A	96-	MCS 800					MCS 800
ST	50	Dax	ST50	78-87	MCS 800					MCS 800
ST	50	Dax	AB23	88-93	MCS 800					MCS 800
SZX	50	X8R-S, X8R-X	AF49	98-	MCB 674	SR	RQ			MCB 686
XL	50		XL50	79-	MCS 804					MCS 804
XR	50	R		00-	MCS 827					MCS 827
Z	50	A	Z50A	71-79	MCS 800					MCS 800
Z	50	G	AB02	79-	MCS 800					MCS 800
Z	50	J	AE02	79-85	MCS 800					MCS 800
Z	50	R	AB02	79-80	MCS 827					MCS 827
Z	50	R	AB020	81-86	MCS 827					MCS 827
ZB	50	P	AB22	88-	MCB 589					MCS 827
ST	70	K3			MCS 800					MCS 800
CRM	75				MCB 574 SI	RSI				MCB 575 SI
CRM	75	alternativ mit Trommel			MCB 574 SI	RSI				MCS 804
NS-1	75			92-	MCB 663					MCB 575 LF
	80	Cityfly		99-	MCB 577					
CB	80		HC03	80-	MCS 804					MCS 804
CR	80	R		86-91	MCB 554 SI					MCS 804





→ **HONDA**

CR	80 R	HE04	92-02	MCB 554 SI				MCB 575 SI	RSI
CR	80 R		82	MCS 804				MCS 825	
CR	80 R		85	MCS 804				MCS 804	
CR	80 R		83-84	MCS 825				MCS 825	
CY	80	CY 80	79-	MCS 800				MCS 800	
MB	80 S	HC01	80-	MCB 522				MCS 804	
MBX	80 SW	HC04	83-	MCB 525				MCS 804	
MBX	80 SW2	HC04	83-87	MCB 510	SI			MCS 804	
MBX	80 SWD	HC04	85-	MCB 510	SI			MCS 804	
MBX	80 SWD	HC04	83-84	MCB 525				MCS 804	
MBX	80 SWZ	HC04	83-84	MCB 525				MCS 804	
MCX	80 S	HC05	83-	MCB 522				MCS 804	
MT	80 S	HD02	80-	MCS 804				MCS 804	
MTX	80	HD06	82-	MCS 804				MCS 804	
MTX	80 R2	HD09	87-	MCB 534	SI			MCS 804	
MTX	80 RS	HD08	83-84	MCS 804				MCS 804	
NH	80 Lead	HF01	85-	MCB 589				MCS 813	
NH	80 Lead	HF01	83-84	MCS 800				MCS 813	
NSR	80 R		87-92	MCB 525				MCB 575 LF	
XR	80 R		85-	MCS 855				MCS 855	
CR	85 R		03-	MCB 554 SI				MCB 575 SI	
NH	90 Yupy	AF01	90-94	MCB 575 SR				MCS 800	
SRX	90 Shadow	HF09A	98-	MCB 575 SR				MCS 800	
SCV	100 Lead	JF11	00-	MCB 534				MCS 835	
SH	100 Scoopy		96-	MCB 674	SR	RQ		MCS 800	
SJ	100 Bali	HF07A	97-	MCB 673				MCS 800	
XR	100 R		85-	MCS 855				MCS 855	
SCV	110 Lead		08-	MCB 685				MCS 835	
ANF	125 Innova	JC33	03-	MCB 759				MCS 800	
CA	125 Rebel	JC26	97-03	MCB 557				MCS 805	
CA	125 Rebel	JC24	95-96	MCB 689				MCS 805	
CB	125 J	CB125J	75-81	MCB 504				MCS 804	
CB	125 K6		76-	MCB 29				MCS 817	
CB	125 T	CB125T	78-79	MCB 504				MCS 817	
CB	125 T2,T	CB125T	80-81	MCB 502				MCS 817	
CB	125 TD	JC06	82-	MCB 512				MCS 817	
CBF	125		09-	MCB 759					
CBR	125 R		04-	MCB 759				MCB 738 LF	
CG	125		04-	MCB 510					
CG	125		85-04	MCS 819				MCS 800	
CH	125 Spacy	JF03A	94-	MCB 685				MCS 819	
CH	125 Spacy	JF03A	83-84	MCS 800				MCS 800	
CLR	125 Cityfly	JD18B	99-	MCB 557	SR			MCS 804	
CM	125 C	JC05	82-	MCS 803				MCS 817	
CR	125 R	JE01	82					MCS 819	
CR	125 R	JE01	84-85	MCB 534	SI				
CR	125 R	JE01	86	MCB 534	SI				
CR	125 R	JE01	87-94	MCB 574 SI	RSI			MCB 575 SI	RSI
CR	125 R	JE01	95-01	MCB 669 SI	RSI			MCB 575 SI	RSI
CR	125 R		02-	MCB 669 SI	RSI			MCB 730SI	
CRE	125		02-	MCB 669 SI	RSI			MCB 730SI	
CRM	125		90-	MCB 557				MCB 623 LF	
FES	125 Phanteon	JF05	98-02	MCB 692	SV			MCS 995	
FES	125 Phanteon	JF12	03-	MCB 692	SV			MCB 585 LF	SH
FES	125 S-Wing		07-	MCB 776				MCB 806 LF	
FS	125 Sonic		03-	MCB 525					
MBX	125 RW		84	MCB 551				MCS 804	
MTX	125 RW		85-	MCB 534	SI			MCS 804	
MTX	125 RW		83-84	MCS 804				MCS 804	
NES	125 @	JF07	01-	MCB 534				MCS 805	
NH	125 D, Lead	JF01	83-87	MCS 800				MCS 800	
NH	125 Lead	JF01	86-87	MCB 589				MCS 800	
NS	125 F		86-93	MCB 557				MCS 800	
NSR	125 F, R	JC22	90-	MCB 557				MCB 623 LF	
NX	125		89	MCB 574	SI	RSI		MCS 800	
NX	125 , Transcity	JD09	90-98	MCB 557				MCS 800	
PS	125 i		07-	MCB 685				MCS 835	
RS	125 R		95-	MCB 540 SV	SRQ	CRQ		MCB 589	
RS	125 R		88-89	MCB 571	SV			MCB 589	
RS	125 R		90	MCB 598	SV	SRQ		MCB 589	






→ **HONDA**

RS	125 R		91-94	MCB 598	SV	SRQ	MCB 585 LF	SH		
SES	125 Dylan	JF10	02-	MCB 685			MCS 835			
SH	125 ,i	JF09	02-'08	MCB 534			MCS 835			
SH	125 ,i		09-	MCB 776	SV		MCB 806 LF			
VT	125 C Shadow	JC29	99-00	MCB 663			MCS 805			
VT	125 C Shadow	JC31	01-	MCB 663			MCS 805			
XL	125	XL125	73-74	MCS 800			MCS 804			
XL	125	XL125	72	MCS 804			MCS 804			
XL	125 R		85-	MCB 534	SI		MCS 804			
XL	125 S		79-82	MCS 804			MCS 804			
XLR	125	JD	93-	MCB 574	SI	RSI	MCB 575 LF	SI	RSI	
XLR	125 R	JD	98-	MCB 574	SI	RSI	MCS 804			
XLV	125 Varadero	JC32	01-	MCB 663			MCB 738 LF			
XR	125 L	JD19	03-	MCB 669	SV		MCS 804			
CRF	150 R		07-	MCB 561 SI			MCB 730 SI	RSI		
FES	150 Phanteon	JF05	98-02	MCB 692	SV		MCS 995			
FES	150 Phanteon	KF06	03-	MCB 692	SV		MCB 585 LF	SH		
NES	150 @	KF03	01-	MCB 534			MCS 835			
NSR	150		02-	MCB 663	SR		MCB 582	SI	RSI	
PS	150 i		06-	MCB 685			MCS 835			
SES	150 Dylan	JF10	02-	MCB 685			MCS 835			
SH	150	KF04	02-	MCB 534			MCS 835			
SH	150 ,i		09-	MCB 776	SV		MCB 806 LF			
CM	185 T	CM185T	79	MCS 803			MCS 817			
XL	185 S	L185S	79-81	MCS 804			MCS 804			
CB	200 B	CB200	81	MCB 29			MCS 811			
CM	200 T	MC01	80-81	MCS 803			MCS 817			
MTX	200 RW	MD07	85-	MCB 534	SI		MCS 804			
MTX	200 RW	MD07	83-84	MCS 804			MCS 804			
XL	200 R	MD06	83-	MCS 804			MCS 804			
XR	200		81-83	MCS 804			MCS 804			
	250 Forza		00-04	MCB 704	SV		MCB 634 LF			
	250 Forza		05-	MCB 776	SV		MCB 806 LF			
	250 Jazz		00-	MCB 704	SV					
ATC	250 R		81	MCB 510 SI *						
ATC	250 R		85	MCB 534 SI *			MCB 538 SI			
ATC	250 R		85-86	MCB 534 SI *			MCB 534 SI			
ATC	250 R		82-84	MCB 554 SI *			MCB 538 SI			
CB	250 G	CB250	74-76	MCB 35			MCS 802			
CB	250 N ,ND	CB250N	79-82	MCB 55			MCS 807			
CB	250 RS	MC02	85-	MCB 534			MCS 811			
CB	250 RS	MC02	80-84	MCB 55			MCS 811			
CB	250 T2	CB250T	79-	MCB 55			MCS 807			
CB	250 Two-fifty		92-	MCB 598	SV		MCS 807			
CBF	250		04-	MCB 663			MCS 835			
CH	250 Spacy		85-	MCB 534			MCS 820			
CJ	250 T	CJ250T	77-78	MCB 35			MCS 802			
CL	250 S	MD04	82-	MCS 803			MCS 811			
CM	250 C	MC06	82-	MCS 803			MCS 817			
CMX	250 Rebel		98-	MCB 673			MCS 817			
CMX	250 Rebel	MC13B	96-97	MCB 689			MCS 817			
CN	250		93-	MCB 544			MCS 819			
CN	250 Helix	MF02	88-92	MCB 544			MCS 831			
CN	250 Helix-Fusion	MF02	92	MCB 544			MCS 820			
CR	250 R	ME03	81-83				MCS 819			
CR	250 R	ME03	84-85	MCB 534 SI						
CR	250 R	ME03	86	MCB 534 SI						
CR	250 R	ME03	87-94	MCB 574 SI	RSI		MCB 575 SI	RSI		
CR	250 R	ME03	95-01	MCB 669 SI	RSI		MCB 575 SI	RSI		
CR	250 R	ME03	02-04	MCB 669 SI	RSI		MCB 730 SI	RSI		
CRF	250 R		04-	MCB 669 SI	RSI		MCB 730 SI	RSI		
CRE	250		02-	MCB 669 SI	RSI		MCB 730 SI	RSI		
CRM	250 R		89-90	MCB 574 SI	RSI		MCB 601 LF			
CRM	250 R		91-	MCB 574 SI	RSI		MCB 575 SI	RSI		
EX	250 Sporttrax		01-	MCB 561 SI *						
EX	250 Sporttrax		01-	MCB 561 SI *						
FES	250 Foresight	MF05	00-	MCB 693			MCB 585 LF	MCS 995	Hand brake	
FES	250 Foresight	MF04	98-99	MCB 693			MCS 995	MCS 995	Hand brake	
NSR	250 R		87	MCB 562 SV *	SRQ		MCB 512 LF			





→ HONDA

NSR	250 R		88-	MCB 593 SV *	SRQ	CRQ		MCB 585 LF		
NSS	250 Forza		00-04	MCB 704	SV					
NSS	250 Forza, ABS		05-	MCB 776 SV				MCB 806 LF		
NX	250	MD21	88-90	MCB 574	SI	RSI		MCS 812		
NX	250	MD25	91-95	MCB 574	SI	RSI		MCS 812		
PS	250 Ruckus		05-	MCB 776	SV			MCS 995		
RS	250 R		93	MCB 540 SV	SRQ	CRQ		MCB 589		
RS	250 R		91-	MCB 593 SV	SRQ	CRQ		MCB 585 LF	SH	
RS	250 R		90-93	MCB 598 SV *	SRQ			MCB 585 LF	SH	
VTR	250	MC15	98-	MCB 677				MCB 585 LF	SH	
XL	250	L250	73-74					MCS 804		
XL	250 R	MD11	84-85	MCB 534	SI			MCS 804		
XL	250 R	L250S	90-	MCS 803				MCS 805		
XL	250 R	MD03	82	MCS 819				MCS 812		
XL	250 RE		90-	MCB 574	SI	RSI		MCB 575 LF	SI	
XL	250 S	L250S	79-81	MCS 803				MCS 812		
XLR	250 R		94-	MCB 669	SV	RSI	SI	MCB 575 LF	SI	
XR	250 R		81-83					MCS 812		
XR	250 R	ME06	84-87	MCB 534	SI			MCS 804		
XR	250 R, RK	ME06	88-93	MCB 574	SI	RSI		MCB 575 LF	SI	
XR	250 S, R	ME06	94-	MCB 669	SI	RSI		MCB 575 LF	SI	
EX	300 Sporttrax		01-	MCB 561 SI *				MCB 561 SI		
SH	300 i, ABS		07-	MCB 776 SV				MCB 806 LF		
TRX	300 EX		93-05	MCB 561 SI *				MCB 561 SI		
ATC	350 X		85	MCB 534 SI *				MCB 538 SI		
ATC	350 X		86-	MCB 574 SI *				MCB 538 SI		
CB	350 F	CB350F	73-76	MCB 35				MCS 802		
TRX	350 G-N		86-93	MCS 823				MCS 823		
XL	350 R	ND03	85-87	MCB 534	SI			MCS 812		
XR	350 R		84-	MCB 534	SI			MCS 804		
XR	350 RD		84					MCS 804		
CB	360 G	CB360	73-76	MCB 35				MCS 802		
CJ	360 T	CJ360T	76-78	MCB 35				MCS 807		
CB	400 A	CB400N	77-81	MCB 55				MCS 807		
CB	400 F	CB400F	75-77	MCB 35				MCS 802		
CB	400 Four	CB400F	81-	MCB 512 *				MCS 807		
CB	400 Four	NC36	97-98	MCB 598 *	SV			MCB 585 LF	SH	
CB	400 N	CB400N	82-	MCB 512 *				MCS 807		
CB	400 N	CB400N	78-81	MCB 54 *				MCS 807		
CB	400 Super Four S		97-	MCB 698 *				MCB 585 LF		
CB	400 Twin	CB400T	82-	MCB 512				MCS 807		
CB	400 Twin	CB400T	77-81	MCB 55				MCS 807		
CB-1	400 F	NC27	89-90	MCB 598	SV	SRQ		MCB 585 LF	SH	
CBR	400 RR	NC29	89-	MCB 598 *	SV	SRQ		MCB 585 LF	SH	
CM	400 T	NC01	82-	MCB 512				MCS 807		
CM	400 T	NC01	79-81	MCB 55				MCS 807		
FJS	400 Silver Wing	NF01	06-	MCB 704	SV			MCB 764 LF		
FJS	400 Silver Wing	Parkingbrake	06-	MCB 647						
NSR	400 R	NC19	85-	MCB 544 *				MCB 512 LF		
SWT	400 , C-ABS		09-	MCB 776	SV			MCB 631 LF	SH	
SWT	400 , C-ABS	Parkingbrake	09-	MCB 647						
TRX	400 EX		99-	MCB 561 SI *				MCB 561 SI		
VFR	400 R	NC24	-88	MCB 562 *	SV	SRQ		MCB 585 LF	SH	
VFR	400 R	NC30	89-	MCB 593 *	SV	SRQ	CRQ	MCB 594 LF		
XR	400 R		96-	MCB 669	SI	RSI	SV	MCB 575 LF	SI	RSI
XR	400 Supermotard		00-	MCB 669	SI	RSI	SV	MCB 575 LF	SI	RSI
TRX	420 Fourtrax Rancher AT		09-	MCB 561 SI *				MCB 769 SI		
XR	440 R		00-	MCB 669	SV	RSI	SI	MCB 575 LF	SI	RSI
CB	450		73-74	MCB 32				MCS 809		
CB	450		75-77	MCB 35				MCS 809		
CB	450 N	PC14	84-85	MCB 537				MCS 807		
CB	450 N	PC14	86-	MCB 570				MCS 807		
CB	450 S	PC17	86-89	MCB 562 *				MCS 807		
CRF	450 R	PE05	02-08	MCB 669 SI	RSI			MCB 730 SI	RSI	
CRF	450 Efi		09-	MCB 669 SI	RSI			MCB 730 SI	RSI	
CRE	450	HM-Italy		MCB 669 SI	RSI			MCB 730 SI	RSI	
CRM	450	HM-Italy	07-	MCB 794 SRQ	RSI			MCB 730 SI	RSI	
EX	450 Sporttrax		01-	MCB 561 SI *				MCB 561 SI		
TRX	450 R		04-	MCB 669 *	SI			MCB 769 SI		
CRE	490 F	HM-Italy	07-	MCB 669 SI	RSI			MCB 730 SI	RSI	
CB	500	CB500	70-74	MCB 35				MCS 809		






→ **HONDA**

CB	500	PC26	94-96	MCB 598	SV			MCS 806	
CB	500 S	PC32	97-	MCB 671	SV			MCB 672 LF	SH
CB	500 T		75	MCB 35				MCS 809	
CBF	500	PC39	04-	MCB 677	SV			MCB 634 LF	SH
CBF	500 ABS	PC39	04-	MCB 776 SV				MCB 634 LF	SH
CR	500 R	PE020	84-85	MCB 534 SI					
CR	500 R	PE02	86	MCB 534 SI					
CR	500 R	PE02	87-94	MCB 574 SI	RSI			MCB 575 SI	RSI
CR	500 R	PE02	95-	MCB 669 SI	RSI			MCB 575 SI	RSI
CX	500	CX 500	79-81	MCB 54 *				MCS 806	
CX	500 C	PC01	80-81	MCB 512 *				MCS 806	
CX	500 E	PC06	82-	MCB 544				MCB 544 LF	
CX	500 TC	PC03	82-	MCB 512 *				MCB 544 LF	
FT	500 C	PC07	82-	MCB 512				MCB 512 LF	
GB	500 Clubmann	PC16	88-	MCB 512				MCS 821	
GL	500 D	PC02	81-85	MCB 512 *				MCS 806	
TRX	500 Fourtrax		05-	MCB 823 SI *				MCS 806	
VF	500 F	PC12	84-86	MCB 544 *				MCB 512 LF	
VF	500 F2	PC12	84-86	MCB 544 *				MCB 512 LF	
VT	500 C	PC08	83-86	MCB 512				MCS 807	
VT	500 E	PC11	83-	MCB 526				MCS 807	
XBR	500 S	PC15	85-88	MCB 512				MCS 821	
XL	500 R	PD02	82-	MCS 815				MCS 805	
XL	500 S	PD01	79-80	MCS 810				MCS 805	
XL	500 S	PD01	81	MCS 810				MCS 811	
XR	500 R		81-82					MCS 805	
XR	500 R	PE03	83-84	MCB 534	SI			MCS 805	
CB	550 F1,F2,K3	CB550K	-78	MCB 35				MCS 809	
CBX	550 F,F2		82-	MCB 526 *				MCB 543 LF	
CB	600 Hornet	PC34	98-01	MCB 598 *	SV	SRQ		MCB 634 LF	SH
CB	600 Hornet	PC36	02-06	MCB 598 *	SV	SRQ		MCB 634 LF	SH
CB	600 Hornet	PC41	07-	MCB 598 SV *				MCB 784 LF	SH
CB	600 Hornet ABS	PC41	07-	MCB 776 SV *				MCB 634 LF	SH
CBF	600 N, S, ABS	PC38	04-07	MCB 598 *	SV	SRQ		MCB 634 LF	SH
CBF	600 N, S, ABS		08-	MCB 776 SV *				MCB 634 LF	SH
CBR	600 F	PC19	87-88	MCB 562 *	SV	SRQ		MCB 512 LF	
CBR	600 F	PC23	89-90	MCB 562 *	SV	SRQ		MCB 512 LF	
CBR	600 F	PC25	91-92	MCB 562 *	SV	SRQ		MCB 634 LF	SH
CBR	600 F	PC25	93-94	MCB 562 *	SV	SRQ		MCB 634 LF	SH
CBR	600 F	PC31	95-98	MCB 598 *	SV	SRQ		MCB 634 LF	SH
CBR	600 F	PC35	99-	MCB 703 SV *	SRQ	CRQ		MCB 634 LF	SH
CBR	600 RR	PC37	03-04	MCB 703 SV *	SRQ	CRQ		MCB 634 LF	SH
CBR	600 RR	PC37	05-06	MCB 755 SV *	SRQ	CRQ	SCR	MCB 634 LF	SH
CBR	600 RR	PC40	07-08	MCB 755 SV *	SRQ	CRQ	SCR	MCB 784 SH	
CBR	600 RR, ABS		09-	MCB 755 SV *	SRQ	CRQ	SCR	MCB 784 SH	
FJS	600 Silver Wing, ABS	PF01	01-	MCB 704	SV			MCB 764 SH	
VT	600 C	PC21	88	MCB 571				MCS 806	
VT	600 C	PC21	94-01	MCB 598	SV			MCS 806	
VT	600 C	PC21	89-93	MCB 624	SV			MCS 806	
XL	600 LM	PD04	85-	MCB 512				MCS 805	
XL	600 R	PD03	83-87	MCB 534	SI			MCS 805	
XL	600 RM	PD04	86-	MCB 512				MCS 805	
XL	600 V Transalp	PD06	87-90	MCB 512	SV			MCS 805	
XL	600 V Transalp	PD06	91-93	MCB 571	SV			MCB 585 LF	SH
XL	600 V Transalp	PD06	94-96	MCB 677	SV			MCB 585 LF	SH
XL	600 V Transalp	PD10	97-01	MCB 669 *	SV			MCB 585 LF	SH
XR	600 R	PE04	83-87	MCB 534	SI			MCS 805	
XR	600 R	PE04	88-90	MCB 574	SI	RSI		MCS 804	
XR	600 R	PE04	91-92	MCB 574	SI	RSI		MCB 575 LF	SI
XR	600 R	PE04	93-	MCB 574	SI	RSI		MCB 575 LF	SI
CB	650	RC03	79-81	MCB 55 *				MCS 808	
CB	650 C	RC05	80-	MCB 55				MCS 808	
CB	650 SC	RC08	83-	MCB 512 *				MCB 543 LF	
CBX	650 E	RC13	83-	MCB 512 *				MCS 806	
CX	650 C	RC11	83-	MCB 512 *				MCS 806	
CX	650 E	RC12	83-	MCB 544 *				MCB 512 LF	
CX	650 Turbo	RC16	83-	MCB 512 *				MCB 512 LF	
FMX	650	RD12	04-	MCB 598	SV			MCB 585 LF	SH
FX	650 Vigor	RD09	99-02	MCB 671	SV			MCB 672 LF	SH
GL	650 D	RC10	83-85	MCB 544 *				MCS 806	
NT	650 V Deauville	RC47	98-00	MCB 671 *	SV			MCB 585 LF	SH





→ HONDA

NT	650	V Deauville	RC47	01	MCB 671	*	SV			MCB 634 LF	SH
NT	650	V Deauville	RC47	02-05	MCB 704	*	SV			MCB 705 LF	SH
NTV	650	Revere	RC33	88-97	MCB 598		SV			MCB 585 LF	SH
NX	650	Dominator	RD02	90-95	MCB 571		SV			MCB 585 LF	SH
NX	650	Dominator	RD02	88-89	MCB 624		SV			MCB 585 LF	SH
NX	650	Dominator	RD08	96-01	MCB 671		SV			MCB 672 LF	SH
SLR	650		RD09	97-98	MCB 671		SV			MCB 672 LF	SH
TRX	650	Rincon		03-						MCB 769 SI	
XL	650	V Transalp	RD10	99-01	MCB 669	*	SV			MCB 585 LF	SH
XL	650	V Transalp	RD11	02-04	MCB 669	*	SV			MCB 585 LF	SH
XR	650	L	RD062	93-97	MCB 669		SV	RSI	SI	MCB 575 LF	SI
XR	650	R	RE01	00-	MCB 669		SV	SI	RSI	MCB 575 LF	SI
XRV	650	Afrika Twin	RD03	88-	MCB 624		SV			MCB 585 LF	SH
DN-01	680		RC55	08-	MCB 776 SV	*				MCB 599 LF	SH
TRX	680	Fourtrax		06-	MCB 823 SI	*				MCB 769 SI	
NT	700	Deauville ABS	RC52	06-	MCB 776 SV					MCB 705 LF	SH
TRX	700	Fourtrax		08-	MCB 669 SI					MCB 823 SI	
XL	700	Transalp	RD13	08-	MCB 776 SV	*				MCB 634 LF	SH
CB	750	C	RC06	82-	MCB 537	*				MCS 808	
CB	750	C	RC06	80-81	MCB 55	*				MCS 808	
CB	750	F	CB750F	75-76	MCB 35					MCB 63 LF	
CB	750	F	CB750G	77-78	MCB 54					MCB 63 LF	
CB	750	F1	RC04	80-81	MCB 54	*				MCB 54 LF	
CB	750	F2	RC04	82-	MCB 512	*				MCB 512 LF	
CB	750	K	RC01	82-	MCB 512	*				MCS 808	
CB	750	K1-K6	CB750	71-77	MCB 32					MCS 808	
CB	750	K7	CB750K	78-	MCB 35					MCS 808	
CB	750	KZ	RC01	80-81	MCB 55	*				MCS 808	
CB	750	Seven Fifty	RC42	92-01	MCB 598	*	SV			MCB 634 LF	SH
CBX	750	F	RC17	84-	MCB 512	*				MCB 512 LF	
NR	750		NC40	92-	MCB 593	*	SV	SRQ		MCB 585 LF	SH
RVF	750	R	RC45	94-97	MCB 593	*	SV	SRQ		MCB 594 LF	
VF	750	C	RC09	82-92	MCB 512	*				MCS 806	
VF	750	C	RC43	93-99	MCB 598		SV			MCS 822	
VF	750	F	RC15	83-	MCB 512	*				MCB 512 LF	
VF	750	S	RC07	82-	MCB 512	*				MCS 806	
VFR	750	F	RC24	86-87	MCB 571	*	SV			MCB 512 LF	
VFR	750	F	RC24	88-89	MCB 598	*	SV	SRQ		MCB 599 LF	SH
VFR	750	F	RC36	90-97	MCB 598	*	SV	SRQ		MCB 599 LF	SH
VFR	750	R	RC30	88-89	MCB 593 SV	*	SRQ	CRQ		MCB 594 LF	
VFR	750	R	RC30	90-93	MCB 593 SV	*	SRQ	CRQ		MCB 594LF	
VT	750	Black Widow	RC48	01-	MCB 677		SV			MCS 822	
VT	750	C	RC29	87-	MCB 512					MCS 822	
VT	750	C	RC29	83-86	MCB 537					MCS 806	
VT	750	C Shadow Spirit A.C.E.	RC44	97-07	MCB 677		SV			MCS 806	
XLV	750	R	RD01	88-	MCB 512					MCS 821	
XRV	750	Afrika Twin	RD04	90-92	MCB 562	*	SV			MCB 585 LF	SH
XRV	750	Afrika Twin	RD07	93-	MCB 669	*	SV			MCB 585 LF	SH
PC	800	Pacific Coast	RC34	95-	MCB 598	*	SV			MCS 822	
VFR	800		RC46	98-01	MCB 704	*	SV			MCB 705 LF	SH
VFR	800	V-TEC, ABS	RC46	02-05	MCB 704	*	SV			MCB 705 LF	SH
VFR	800	Interceptor, ABS	RC46	06-	MCB 776 SV	*				MCB 705 LF	SH
CB	900	F	SC01	79-81	MCB 54	*				MCB 54 LF	
CB	900	F,F2	SC01	81-	MCB 512	*				MCB 512 LF	
CB	900	F,F2	SC09	82-	MCB 512	*				MCB 512 LF	
CB	900	Hornet	SC48	02-	MCB 593	*	SV	SRQ		MCB 634 LF	SH
CBR	900	RR	SC28	92-95	MCB 593 SV	*	SRQ	CRQ		MCB 634 LF	SH
CBR	900	RR	SC33	96-97	MCB 593 SV	*	SRQ	CRQ		MCB 634 LF	SH
CBR	900	RR	SC33D	98-99	MCB 703 SV	*	SRQ	CRQ		MCB 634 LF	SH
CBR	900	RR	SC44	00-01	MCB 703 SV	*	SRQ	CRQ		MCB 634 LF	SH
CBR	954	RR Fireblade	SC50	02-03	MCB 703 SV	*	SRQ	CRQ		MCB 634 LF	SH
CB	1000	Super Four	SC30	93-03	MCB 593 SV	*	SRQ	CRQ		MCB 634 LF	SH
CB	1000	R	SC60	08-	MCB 755 SV	*	SRQ	CRQ		MCB 817 SH	
CBF	1000		SC58	06-	MCB 677	*	SV			MCB 634 LF	SH
CBF	1000	ABS	SC58	06-	MCB 776 SV	*				MCB 776 SH	
CBR	1000	F	SC21	87-88	MCB 571	*	SV			MCB 512 LF	
CBR	1000	F	SC24	89	MCB 598	*	SV	SRQ		MCB 599 LF	
CBR	1000	F	SC24	90-92	MCB 598	*	SV	SRQ		MCB 631 LF	SH
CBR	1000	F, Dual CBS	SC24	93-01	MCB 658	*	SV			MCB 658	SV
CBR	1000	RR Fireblade	SC57	04-05	MCB 755 SV	*	SRQ	CRQ	SCR	MCB 634 LF	SH
CBR	1000	RR Fireblade	SC57	06-07	MCB 755 SV	*	SRQ	CRQ	SCR	MCB 784 SH	





→ **HONDA**

CBR	1000	RR Fireblade	SC59	08-	MCB 755 SV *	SRQ	CRQ	SCR	MCB 784 SH		
CBX	1000		CB1	79	MCB 54 *				MCB 54 LF		
CBX	1000		SC06	81-	MCB 544 *				MCB 512 LF		
GL	1000		GL1, GL2	78	MCB 54 *				MCB 63 LF		
GL	1000		GL1, GL2	81-	MCB 54 *				MCB 54 LF		
GL	1000		GL1, GL2	75-77	MCB 62 *				MCB 63 LF		
VF	1000		SC15	84-	MCB 512 *				MCB 512 LF		
VF	1000	F2	SC15	85-	MCB 512 *				MCB 512 LF		
VF	1000	R	SC16	84-85	MCB 512 *	SV			MCB 545 LF		
VF	1000	R	SC16	86-	MCB 512 *	SV			MCB 512 LF	SH	
VTR	1000	Firestorm	SC36	97-	MCB 593 SV *	SRQ	CRQ		MCB 634 LF	SH	
VTR	1000	SP-1	SC45	00-01	MCB 703 SV *	SRQ	CRQ		MCB 634 LF	SH	
VTR	1000	SP-2	SC45	02-07	MCB 703 SV *	SRQ	CRQ		MCB 634 LF	SH	
XL	1000	Varadero ABS	SD02	04-	MCB 776 SV *				MCB 705 LF	SH	
XL	1000	Varadero Dual CBS	SD01	99-	MCB 704 *	SV			MCB 705 LF	SH	
CB	1100	F	SC11	83-	MCB 512 *				MCB 512 LF		
CB	1100	R	SC05	81-	MCB 512 *				MCB 512 LF		
CB	1100	R	SC08	82-	MCB 512 *				MCB 512 LF		
CB	1100	X-Eleven	SC42	00-	MCB 704 *	SV			MCB 705 LF		
CBR	1100	XX	SC35	98-	MCB 704 *	SV			MCB 705 LF	SH	
GL	1100		SC02	80	MCB 54 *				MCB 54 LF		
GL	1100	D	SC02	81-	MCB 512 *				MCB 512 LF		
ST	1100	ABS-TCS-CBS	SC26	92-95	MCB 598 *	SV			MCB 631 LF	SH	
ST	1100	ABS-TCS-CBS	SC26	96-	MCB 692 *	SV			MCB 693 LF		
ST	1100	Pan European	SC26	90-	MCB 598 *	SV			MCB 631 LF	SH	
VF	1100	C	SC12	83-	MCB 512 *				MCB 512 LF		
VT	1100	C1	SC23	85-89	MCB 512 *				MCS 822		
VT	1100	C1	SC23	94	MCB 512 *	SV			MCS 822		
VT	1100	C2	SC32	95-99	MCB 598 *	SV			MCB 634 LF	SH	
VT	1100	C3	SC39	98-	MCB 598 *	SV			MCB 634 LF	SH	
GL	1200	D	SC14	84-	MCB 512 *				MCB 512 LF		
CB	1300	R	SC54	02-	MCB 703 *	SV	SRQ		MCB 634 LF	SH	
CB	1300	SF	SC40	98-	MCB 660 SV *	SRQ			MCB 634 LF	SH	
CB	1300	X-4	SC38	97-	MCB 593 *	SV			MCB 691 LF	SH	
STX	1300	Pan European, ABS	SC51	02-	MCB 704 *	SV			MCB 705 LF	SH	
VTX	1300	C, S	SC52	03-	MCB 598 *	SV			MCB 634 LF	SH	
GL	1500		SC22	88-97	MCB 624 *	SV			MCB 512 LF		
GL	1500	A, I	SC22	94-97	MCB 624 *	SV			MCB 512 LF	SH	
GL	1500	SE	SC22	91-00	MCB 624 *	SV			MCB 512 LF	SH	
GL	1520	F6C Valkyrie	SC34B	97-	MCB 598 *	SV			MCB 599 LF	SH	
GL	1800	Gold Wing	SC47	01-	MCB 704 *	SV			MCB 705 LF	SH	
VTX	1800		SC46	01-	MCB 704 *	SV			MCB 705 LF	SH	