

Suzuki

	50	Lido		91-	MCB 569	SV			MCB 615	SH	
	50	Lido	CS50H	89-	MCS 921				MCS 921		
A	50	K		75-	MCS 854				MCS 854		
AH	50	Address	CA1GA	93-95	MCS 920				MCS 920		
AP	50			71-78	MCS 854				MCS 854		
AP	50	S	CA1JA	95-	MCB 674	SR	RQ		MCS 921		
AY	50	Katana	AA	97-98	MCB 674	SR	RQ		MCS 921		
AY	50	WR Katana	AJP	AA	01-	MCB 535	SR	RQ	MCB 535	SR	
AY	50	WR Katana	Grimeca	AA	99-	MCB 674	SR	RQ	MCB 535	SR	
GT	50		GT50	79-	MCB 16				MCS 854		
GT	50			77-	MCB 91				MCS 854		
GT	50	E	GT50E	79-	MCB 16				MCS 854		
GT	50	K	GT50K	79-	MCB 91				MCS 854		
GT	50	KE	GT50K	79-	MCB 16				MCS 854		





→ **SUZUKI**

RMX	50		00-	MCB 535			MCB 535	SR
TR	50 S		98-	MCB 519	SR		MCS 990	
TR	50 Street Magic	AH	97-00	MCB 679	SR		MCS 990	
TS	50 ERK	TS50XK	80-83	MCS 854			MCS 901	
TS	50 K	TS50K	78-79	MCS 854			MCS 854	
UF	50 Estilete	WVBA	00-01	MCB 535	SR		MCS 921	
UX	50 W Zillion	AT	99-	MCB 674	SR		MCS 921	
ZR	50 K	ZR50K	79-	MCB 16			MCS 854	
RM	60		03-	MCS 857			MCS 857	
RM	65		03-	MCB 714 SI			MCB 561 SI	
AH	80		92-	MCB 519	SR		MCS 921	
CP	80		85-	MCS 921			MCS 921	
GT	80 E,L	GT80	81-83	MCB 523			MCS 854	
RG	80 C	NC11A	85-87	MCB 556			MCS 855	
RG	80 Gamma	NC11A	88-95	MCB 556			MCS 855	
RM	80		89-93	MCB 519 SI			MCB 519 SI	
RM	80		86-88	MCB 522			MCS 963	
RM	80		94-95	MCB 582 SI	RSI	SV	MCB 519 SI	
RM	80	RC12A	96-01	MCB 679 SI			MCB 519 SI	
RM	80	RC11	83-85	MCS 855			MCS 901	
RM	80		80-81	MCS 901			MCS 901	
TS	80 ER	TS80	81-82	MCS 855			MCS 901	
RM	85		02-04	MCB 679 SI			MCB 519 SI	
RM	85		05-	MCB 758 SI	RSI		MCB 772 SI	RSI
RV	90	RV90	73-77	MCS 854			MCS 854	
AH	100 Address	CE12A	92-	MCB 519	SR		MCS 990	
RM	100		03-	MCB 697 SI			MCB 561 SI	
TS	100 ER		82-	MCS 855			MCS 901	
UG	110 Hokuto		98-02	MCB 679	SR		MCS 990	
	125 Lido Vario	CF41BH	90-	MCB 522			MCS 921	
	125 Vecstar		96-	MCB 679	SR		MCS 921	
AN	125	CF42A	94-00	MCB 679	SR		MCS 921	
DR	125 S	SF42A	85-93	MCB 510	SI		MCS 855	
DR	125 S	SF42A	82-84	MCS 855			MCS 855	
DR	125 SE	SF43B	94-95	MCB 510	SI		MCS 855	
DR	125 SE	SF44A	96-01	MCB 510	SI		MCS 855	
DR	125 SM		08-	MCB 669 SI	RSI		MCB 739 SI	RSI
DR-Z	125		04-	MCB 679	SI		MCS 901	
EN	125		05-	MCB 582	SV		MCS 855	
GN	125 R	NF41A	94-04	MCB 523			MCS 855	
GP	125	GP125	77-	MCB 513			MCS 855	
GS	125 E, ESD	AW	83-	MCB 765			MCS 855	
GT	125	GT125	74-77	MCB 16			MCS 855	
GT	125 E	GT125	78-79	MCB 16			MCS 855	
GV	125 Z, E		82-90	MCB 765				
GV	125		05-	MCB 765				
GZ	125 Marauder	AP	98-	MCB 550			MCS 855	
RG	125 Gamma		85-90	MCB 556			MCS 855	
RG	125 Gamma		91-	MCB 602	SV		MCB 531 LF	SH
RM	125	RM125	75-80	MCS 855			MCS 855	
RM	125		81-83	MCS 855			MCS 915	
RM	125	RF12A	84				MCS 915	
RM	125		85-86	MCB 550			MCS 915	
RM	125	RF13A	87	MCB 582 SI	RSI		MCS 915	
RM	125	RF13A	88	MCB 582 SI	RSI		MCB 538 SI	
RM	125	RF14A	89-93	MCB 582 SI	RSI		MCB 625 SI	RSI
RM	125	RF14A	94-95	MCB 582 SI	RSI		MCB 625 SI	RSI
RM	125	RF15A	96-04	MCB 669 SI	RSI		MCB 575 SI	RSI
RM	125		05-	MCB 669 SI	RSI		MCB 575 SI	RSI
RV	125	RV125	73	MCS 854			MCS 855	
RV	125	RV125	74-81	MCS 855			MCS 855	
RV	125 Van Van	WVBT	03-	MCB 681	SV		MCS 854	
TS	125		85-	MCB 510	SI			
TS	125	TS125	72	MCS 854			MCS 855	
TS	125	TS1252	73-81	MCS 855			MCS 855	
TS	125 ER	TS1252	79-81	MCS 855			MCS 855	
TS	125 R		90-96	MCB 582	SI	SV	MCB 625 SI	
TU	125 XT	AZ	99-	MCB 523	SI		MCS 855	
UC	125 Epicuro	AX	99-02	MCB 679	SR		MCS 823	





→ **SUZUKI**

UE	125		WVBH	01-	MCB 519	SR				MCS 921		
UX	125	SIXteen		08-	MCB 776 SV					MCB 746 LF		
UH	125	Burgman	BP	02-06	MCB 648	SV				MCB 700 LF	SR	
UH	125	Burgman		07-	MCB 776 SV					MCB 724 LF		
VL	125	Intruder LC	WVA4	02-	MCB 550					MCS 855		
VL	125	Intruder LC	A4	99-01	MCB 550					MCS 855		
	150	Vecstar		96-	MCB 679	SR				MCS 921		
AN	150			98-	MCB 679	SR				MCS 921		
UE	150	CT	BJ	02-	MCB 519	SR				MCS 823		
UH	150	Burgman		04-	MCB 648	SV				MCB 700 LF	SR	
UX	150	SIXteen		08-	MCB 776 SV					MCB 746 LF		
LT-F	160			91-01	MCS 921					MCS 902		
GT	185		GT185	73-75	MCB 16					MCS 855		
GT	185	E	GT185	78-	MCB 16					MCS 855		
TS	185		TS185	73-	MCS 854					MCS 855		
TS	185	ER	TS1852	79-	MCS 855					MCS 855		
DR	200	K		89-	MCB 510	SI				MCS 855		
GT	200	N, E	GT200	79-81	MCB 72					MCS 855		
TS	200	R		89-	MCB 582	SI	SV			MCB 625 SI		
UH	200	Burgman		07-	MCB 776 SV					MCB 724 LF		
AN	250	Burgman	4☐ AN	98-03	MCB 706	SR				MCB 685		
AN	250	Burgman	4☐ AN	04-	MCB 706	SR				MCB 746 LF		
CJ	250	Sky wave	4☐	98-	MCB 706	SR				MCB 685		
DR	250	S	SJ42A	85-88	MCB 510	SI				MCS 855		
DR	250	S		89-94	MCB 582	SI	SV			MCB 625 SI		
DR	250	S	SJ45A	95-	MCB 669	SV	RSI	SI		MCB 625 SI		
GN	250		NJ42AD	85-88	MCB 509					MCS 855		
GN	250		NJ42A	91-93	MCB 509					MCS 907		
GN	250		NJ42A	94-	MCB 509					MCS 855		
GN	250	E	NJ42A,NJ41A	82-83	MCB 509					MCS 907		
GSF	250	Bandit		90-	MCB 569	SV				MCB 531 LF	SH	
GSX	250		GS25X	80-81	MCB 509					MCS 907		
GSX	250	E	GS25X	81-	MCB 509					MCB 73 LF		
GSX	250	E, ES	GJ53B	82-83	MCB 501					MCB 73 LF		
GSXR	250			88-	MCB 542	*				MCB 531 LF		
GSXR	250	R		89-	MCB 602	*	SV			MCB 531 LF	SH	
GT	250		GT250	73-78	MCB 16					MCS 904		
GT	250	E	GT2502	79-81	MCB 72					MCS 907		
GZ	250	Marauder	AR	00-	MCB 550					MCS 855		
LT	250	RF Quadracer		85	MCB 523 SI	*				MCB 510 SI		
LT	250	RH/RJ/RK/RL		87-90	MCB 560 SI	*				MCB 626 SI		
LT-F	250	K Ozark		02-	MCB 510 SI	*						
LT-Z	250	QuadSport		04-	MCB 510 Si	*						
RG	250	Gamma	CJ21A	83	MCB 531	*				MCB 531 LF		
RG	250	Gamma	CJ21B	84-	MCB 547	*				MCB 531 LF		
RGV	250			88	MCB 595	*	SV	SRQ		MCB 531 LF		
RGV	250		VJ21A	89-90	MCB 602	*	SV	SRQ		MCB 531 LF		
RGV	250		VJ22B	91-92	MCB 602	*	SV	SRQ	CRQ	MCB 586		
RGV	250		VJ22B	93-	MCB 602	*	SV	SRQ	CRQ	MCB 612 LF		
RH	250			85-	MCB 510	SI						
RM	250		RJ14A	85-	MCB 550							
RM	250		RJ14A	86-	MCB 551							
RM	250		RJ14A	87-88	MCB 582 SI	RSI				MCB 561 SI		
RM	250		RJ14A	89-95	MCB 582 SI	RSI				MCB 625 SI	RSI	
RM	250		RJ14A	94-95	MCB 582 SI	RSI				MCB 625 SI	RSI	
RM	250		RJ18C	96-04	MCB 669 SI	RSI				MCB 575 SI	RSI	
RM	250			05-	MCB 669 SI	RSI				MCB 575 SI	RSI	
RMX	250			89-95	MCB 582 SI	RSI				MCB 625 SI	RSI	
RMX	250			96-98	MCB 669 SI	RSI				MCB 625 SI	RSI	
RMX	250			99-01	MCB 669 SI	RSI				MCB 575 SI	RSI	
RM-Z	250			04-	MCB 669 SI	RSI				MCB 739 SI	RSI	
TS	250		TS 250	71-76	MCB 509					MCS 902		
TS	250		TS2504	77-78	MCS 902					MCS 902		
TS	250	X	SJ11B	85-89	MCB 510	SI						
TU	250	X		97-	MCB 550					MCS 855		
VL	250	Intruder	WVA5	00-	MCB 550					MCS 855		
LT-F	300	F	←	02-	MCB 582 SI					MCS 905		
LT-F	300	F	→	02-	MCB 615 SI					MCS 905		
LT-F	300	F King Quad		99-01						MCS 905		
DR	350	N,S, ES, SE	DK41A	90-96	MCB 582	SI	SV			MCB 625 SI		





→ SUZUKI

DR	350	V,W,X	SK42B	97-	MCB 582	SI	SV		MCB 625 SI			
SP	370		SP370	77-80	MCS 902				MCS 902			
GT	380		GT380	73-77	MCB 16				MCS 904			
AN	400	Burgman	4☐	AU	99-00	MCB 706	SR		MCB 685			
AN	400	Burgman	4☐	WVAU	01-06	MCB 706	SR		MCB 746 LF			
AN	400	Burgman	←		07-	MCB 582	SV		MCB 751 SH			
AN	400	Burgman	→		07-	MCB 615	SV					
DR	400	S		DR400	80-81	MCS 902			MCS 902			
DR-Z	400	S/E		WVBC	00-06	MCB 669	SV	SI	RSI	MCB 575 LF	SI	RSI
DR-Z	400	SM			05-	MCB 669	SV	SI	RSI	MCB 575 LF	SI	
GN	400	T,TD,L		GN400	80-82	MCB 509				MCS 907		
GS	400			GS400	77-78	MCB 70						
GS	400	E		GS400	78-79	MCB 72						
GSF	400	Bandit		GK75B	91-92	MCB 569	*	SV		MCB 531 LF	SH	
GSF	400	Bandit		GK75B	93-94	MCB 602	*	SV		MCB 531 LF	SH	
GSF	400	Bandit		GK75B	95-	MCB 682	*	SV		MCB 531 LF	SH	
GSX	400	E		GK53C	85-	MCB 501				MCS 904		
GSX	400	E		GK53C	82-83	MCB 509				MCS 907		
GSX	400	E, L, S		GS40X	80-81	MCB 509				MCS 907		
GSX	400	F			89-	MCB 591	*	SV		MCB 531 LF	SH	
GSX	400	FE		GS40XF	81	MCB 523	*			MCB 73 LF		
GSX	400	S		GK53C	86-	MCB 501				MCS 904		
GSX	400	S		GK53C	82-	MCB 509				MCS 907		
GSX	400	S		GK53C	83-85	MCB 509				MCS 907		
GSX	400	S, Katana		GK53C	92-	MCB 602	*	SV		MCS 904		
GSXR	400				87	MCB 542	*			MCB 531 LF		
GSXR	400				88-	MCB 602	*	SV	SRQ	CRQ	MCB 531 LF	SH
GSXR	400	R			90-	MCB 595	*	SV	SRQ	CRQ	MCB 531 LF	SH
LT-A	400	FK2 Eiger 4WD		AK	02-	MCB 510 SI	*			☎		
LT-A	400	K2 Eiger		AK	02-	MCB 510 SI	*			☎		
LT-F	400	FK2 Eiger 4WD		AK	02-	MCB 510 SI	*			☎		
LT-F	400	K2 Eiger		AK	02-	MCB 510 SI	*			☎		
LT-Z	400	Quad Sport		AK	03-	MCB 554 SI	*			MCB 626 SI		
GS	450			GS450	80-81	MCB 509				MCS 907		
GS	450			GL51F	90-	MCB 569		SV		MCB 569 LF	SH	
GS	450	E, L, S,		GS450	80-83	MCB 509				MCS 907		
GS	450	S, SU		GL51F	88-89	MCB 501				MCS 907		
GS	450	TU		GS450	81	MCB 509				MCS 907		
LT-R	450		←		06-	MCB 582 SI						
LT-R	450		→		06-	MCB 615 SI						
RM-Z	450				05-07	MCB 669 SI		RSI		MCB 739 SI	RSI	
RM-Z	450	Efi			08-	MCB 669 SI		RSI		MCB 739 SI	RSI	
DR	500	S			89-	MCB 551				MCS 955		
DR	500	S		DR500	81-82	MCS 902				MCS 902		
GS	500			BK	04-	MCB 681		SV		MCB 531 LF	SH	
GS	500	/F		WVBK	04-	MCB 681		SV		MCB 531 LF	SH	
GS	500	E		GM51B	92-96	MCB 569		SV		MCB 531 LF	SH	
GS	500	E		GM51B	97-03	MCB 681		SV		MCB 531 LF	SH	
GS	500	E		GS500E	80-81	MCB 72				MCB 73 LF		
GS	500	E, EU		GM51B	89-91	MCB 569		SV		MCB 531 LF	SH	
GT	500			T500	76-77	MCB 16				MCS 904		
LT	500	R			88-	MCB 519 SI	*					
LT	500	RH Quadzilla			87-	MCB 560 SI	*			MCB 561 SI		
LT	500	RL			90	MCB 560 SI	*			MCB 626 SI		
LT-A	500	FK2 Vinson 4WD			02-	MCB 510 SI	*			MCB 523 SI		
LT-A	500	FY, FK	←		00-01	MCB 582 SI				MCS 905		
LT-A	500	FY, FK	→		00-01	MCB 615 SI						
LT-F	500	F			03-	MCB 510 SI	*			MCB 723 SI		
LT-F	500	F	←		98-02	MCB 582 SI				MCS 905		
LT-F	500	F	→		98-02	MCB 615 SI						
RG	500	Gamma		HM31A	86-89	MCB 542	*			MCB 531 LF		
RM	500				85	MCB 550						
GS	550			GS550	77	MCB 72						
GS	550	D		GS550D	80	MCB 501	*			MCB 73 LF		
GS	550	E		GS550	78-79	MCB 72	*			MCB 73 LF		
GS	550	E, EG		GS550E	80-	MCB 501	*			MCB 73 LF		
GS	550	L		GS550E	80-	MCB 501	*			MCB 73 LF		
GS	550	M		GS550M	81-84	MCB 501	*			MCB 73 LF		
GS	550	T		GS550E	81	MCB 501	*			MCB 73 LF		
GSX	550	E		GN71D	83-86	MCB 531	*			MCB 531 LF		



→ **SUZUKI**

GSX	550	EF		GN71D	84-87	MCB 531	*							MCB 531 LF		
GSX	550	ES		GN71D	83-87	MCB 531	*							MCB 531 LF		
GSX	550	EU		GN71D	85-87	MCB 531	*							MCB 531 LF		
GT	550			GT550	73-75	MCB 16								MCS 904		
GT	550			GT550	76-77	MCB 72										
DR	600	R, RU		SN41A	86-88	MCB 551								MCS 855		
DR	600	R, RU		SN41A	89-	MCB 551								MCB 612 LF		
DR	600	S, SU		SN41AD	85-88	MCB 551								MCS 855		
DR	600	S, SU		SN41AD	89-	MCB 551								MCS 855		
GSF	600	Bandit		GN77B	94-99	MCB 598	*	SV						MCB 531 LF	SH	
GSF	600	Bandit	→	WVA8	00-04	MCB 681		SV	SRQ					MCB 531 LF	SH	
GSF	600	Bandit	←	WVA8	00-04	MCB 682		SV	SRQ							
GSR	600			WVB9	06-	MCB 602	*	SV	SRQ					MCB 783 SH		
GSX	600	F		GN72B	88-97	MCB 591	*	SV						MCB 531 LF	SH	
GSX	600	F	→	AJ	98-04	MCB 681		SV	SRQ							
GSX	600	F	←	AJ	98-04	MCB 682		SV	SRQ					MCB 531 LF	SH	
GSXR	600			WVBG	97-03	MCB 602 SV	*	SRQ	CRQ					MCB 531 LF	SH	
GSXR	600			WVB2	04-05	MCB 752 SV	*	SRQ	CRQ	SCR				MCB 729 LF	SH	
GSXR	600			WVCE	06-07	MCB 752 SV	*	SRQ	CRQ	SCR				MCB 783 SH		
GSXR	600			WVCV	08-	MCB 752 SV	*	SRQ	CRQ	SCR				MCB 783 SH		
RF	600	R, RU		GN76B	93-96	MCB 598	*	SV	SRQ					MCB 531 LF	SH	
VS	600	GLP		VN51B	94-97	MCB 542								MCS 959		
	650	Gladius	→	SFV	09-	MCB 681		SV						MCB 634 LF	SH	
	650	Gladius	←	SFV	09-	MCB 682		SV								
AN	650	Burgman		WVBU	02-	MCB 598	*	SV						MCB 751 LF		
DL	650	V-Strom, ABS	→	WVB1	04-	MCB 681		SV	SRQ							
DL	650	V-Strom, ABS	←	WVB1	04-	MCB 682		SV	SRQ					MCB 634 LF	SH	
DR	650	R, RE		SP44-45B	91-	MCB 597		SV						MCB 612 LF	SH	
DR	650	R, RU		SP41B	90-	MCB 551								MCB 612 LF	SH	
DR	650	RS, RSU		SP42B	91-	MCB 597		SV						MCB 612 LF	SH	
DR	650	RSE, RSEU		SP43B	91-96	MCB 597		SV						MCB 612 LF	SH	
DR	650	SE T-W		SP46B	96-	MCB 669		SV	SI	RSI				MCB 625 SI		
GR	650			GP51A	83-84	MCB 501								MCS 907		
GR	650	X		GP51A	83-89	MCB 501								MCS 907		
GS	650	G		GS650G	81-83	MCB 501	*							MCB 73 LF		
GSF	650	Bandit	→	WVB5	05-	MCB 681		SV	SRQ							
GSF	650	Bandit	←	WVB5	05-	MCB 682		SV	SRQ					MCB 729 LF	SH	
GSF	650	S ABS / ABS		WVCJ	07-	MCB 602		SV	SRQ					MCB 634 LF	SH	
GSX	650	F		WVCJ	08-	MCB 602	*	SV						MCB 634 LF		
LS	650	P Savage		NP41B	86-01	MCB 550								MCS 907		
SV	650	, S	→	AV111	99-02	MCB 681		SV	SRQ					MCB 531 LF	SH	
SV	650	, S	←	AV111	99-02	MCB 682		SV	SRQ							
SV	650	, S	→	WVBY	03-04	MCB 681		SV	SRQ					MCB 634 LF	SH	
SV	650	, S	←	WVBY	03-04	MCB 682		SV	SRQ							
SV	650	, S	→	WVBY	05-	MCB 681		SV	SRQ					MCB 729 LF	SH	
SV	650	, S	←	WVBY	05-	MCB 682		SV	SRQ							
XF	650	Freewind		AC	97-	MCB 681		SV						MCB 585 LF	SH	
	700	Quadrunner	←		04-	MCB 757 SI										
	700	Quadrunner	→		04-	MCB 758 SI										
DR	750	S, SU		SR41B	88	MCB 597		SV						MCS 907		
DR	750	S, SU		SR41B	89-	MCB 597		SV						MCB 612 LF	SH	
GS	750			GS750	77-79	MCB 70								MCB 73 LF		
GS	750	D		GS750D	77-79	MCB 70								MCB 73 LF		
GS	750	E		GS750E	78-79	MCB 70								MCB 73 LF		
GS	750	L		GS750E	79	MCB 72	*							MCB 73 LF		
GSX	750		→	AE	98-02	MCB 681		SV	SRQ					MCB 531 LF	SH	
GSX	750		←	AE	98-02	MCB 682		SV	SRQ							
GSX	750	E		GS75X	80-82	MCB 509	*							MCB 73 LF		
GSX	750	EF		GR72A	85-	MCB 509	*							MCB 73 LF		
GSX	750	EG		GS75X	80-81	MCB 509	*							MCB 73 LF		
GSX	750	ES		GR72A	83-86	MCB 509	*							MCB 73 LF		
GSX	750	F		GR78A	89-97	MCB 591	*	SV						MCB 531 LF	SH	
GSX	750	F	→	AK	98-	MCB 681		SV	SRQ					MCB 531 LF	SH	
GSX	750	F	←	AK	98-	MCB 682		SV	SRQ							
GSX	750	L		GS75X	80-81	MCB 509	*							MCB 73 LF		
GSX	750	S		GR71A	82-	MCB 501	*							MCB 73 LF		
GSXR	750			GR75A	85-87	MCB 542	*							MCB 531 LF		
GSXR	750			GR77B	88-89	MCB 595	*	SV	SRQ	CRQ				MCB 531 LF	SH	
GSXR	750			GR7AB	90-91	MCB 595	*	SV	SRQ	CRQ				MCB 531 LF	SH	
GSXR	750			GR7BB	92-93	MCB 595	*	SV	SRQ	CRQ				MCB 531 LF	SH	



→ SUZUKI

GSXR	750		GR7BB	94-95	MCB 659 SV *	SRQ	CRQ		MCB 531 LF	SH
GSXR	750		GR7DB	96-99	MCB 659 SV *	SRQ	CRQ		MCB 531 LF	SH
GSXR	750		WVBD	00-03	MCB 602 SV *	SRQ	CRQ		MCB 531 LF	SH
GSXR	750		WVB3	04-05	MCB 752 SV *	SRQ	CRQ	SCR	MCB 729 LF	SH
GSXR	750		WVCF	06-07	MCB 752 SV *	SRQ	CRQ	SCR	MCB 783 SH	
GSXR	750		WVCW	08-	MCB 752 SV *	SRQ	CRQ	SCR	MCB 783 SH	
GT	750		GT750	73-77	MCB 16 *				MCS 905	
LT-A	750	King Quad		08-	MCB 787 SI					
LT-A	750	King Quad		08-	MCB 788 SI					
VS	750	GL F,P	VR51BD	86-91	MCB 542				MCS 959	
DR	800	S	SR43B	96-99	MCB 682	SV			MCB 604 LF	
DR	800	SU,S	SR43B	91-96	MCB 569	SV			MCB 615	SH
DR	800	SU,S	SR42B	90	MCB 597	SV			MCB 612 LF	SH
DR-Z	800			88-90	MCB 597	SV			MCB 561 LF	
DR-Z	800	Dzeta		91	MCB 597	SV			MCB 612 LF	SH
M	800	Intruder	WVB4	05-	MCB 681	SV			MCS 959	
VL	800	C, Intruder Volusia	WVBM	01-04	MCB 681	SV			MCS 959	
VS	800	GL	VS52B	92-00	MCB 542				MCS 959	
VX	800	U	VS51B	90-95	MCB 569	SV			MCB 591	SH
VX	800	U	VS51B	96-01	MCB 682 *	SV			MCB 531 LF	SH
VZ	800	Marauder	WVAF	97-04	MCB 681	SV			MCS 959	
GS	850	E, L, G, GL	GS 850	80-82	MCB 509 *				MCB 73 LF	
GS	850	G	GS72A	83-86	MCB 509 *				MCB 73 LF	
GS	850	G	GS 850	79	MCB 70 *				MCB 73 LF	
XN	850		GR71A	83-	MCB 501 *				MCB 73 LF	
RF	900	R	GT73B	94-97	MCB 690 *	SV			MCB 678 LF	SH
DL	1000	V-Strom, ABS	WVBS	02-	MCB 681	SV				
DL	1000	V-Strom, ABS	WVBS	02-	MCB 682	SV			MCB 634 LF	SH
GS	1000	E	GS1000	78-80	MCB 72 *				MCB 73 LF	
GS	1000	E, H	GS1000	80	MCB 72 *				MCB 73 LF	
GS	1000	G, GL	GS100G	80-81	MCB 509 *				MCB 73 LF	
GS	1000	S	GS1000	79-	MCB 501 *				MCB 73 LF	
GSXR	1000		WVBL	01-02	MCB 659 SV *	SRQ	CRQ		MCB 729 SH	
GSXR	1000		WVBZ	03	MCB 742 SV *	SRQ	CRQ	SCR	MCB 729 SH	
GSXR	1000		WVZ	04-06	MCB 752 SV *	SRQ	CRQ	SCR	MCB 729 SH	
GSXR	1000		WVCL	07-08	MCB 752 SV *	SRQ	CRQ	SCR	MCB 783 SH	
GSXR	1000		WVCY	09-	MCB 752 SV *	SRQ	CRQ	SCR	MCB 784 SH	
SV	1000	, S	WVBX	03-	MCB 602 *	SV	SRQ	CRQ	MCB 634 LF	SH
TL	1000	R	AM321	98-00	MCB 659 SV *	SRQ	CRQ		MCB 531 LF	SH
TL	1000	S	AG111	97-00	MCB 602 SV *	SRQ	CRQ		MCB 531 LF	SH
GS	1100	G	GU73A	84-85	MCB 509 *				MCB 73 LF	
GS	1100	G	GU71A	86	MCB 509 *				MCB 73 LF	
GSX	1100		GS110X	80-81	MCB 501 *				MCB 73 LF	
GSX	1100		GU71B	82-	MCB 501 *				MCB 73 LF	
GSX	1100	E	GS110X	81-	MCB 501 *				MCB 73 LF	
GSX	1100	E,EF,ES	GV71C	84-87	MCB 542 *				MCB 542 LF	
GSX	1100	EX	GV71B	83-	MCB 501 *				MCB 73 LF	
GSX	1100	F	GV72C	88-92	MCB 591 *	SV			MCB 542 LF	
GSX	1100	F	GV72C	93-96	MCB 591 *	SV			MCB 531 LF	SH
GSX	1100	G	GV74A	91-93	MCB 569 *	SV			MCB 591	SH
GSX	1100	G	GV74A	94-95	MCB 569 *	SV			MCB 586	
GSX	1100	G	GV74A	96-	MCB 681	SV	SRQ			
GSX	1100	G	GV74A	96-	MCB 682	SV	SRQ		MCB 531 LF	SH
GSXR	1100		GV74CD	86-88	MCB 542 *				MCB 531 LF	
GSXR	1100		GV73C	89-92	MCB 595 *	SV	SRQ	CRQ	MCB 531 LF	SH
GSXR	1100	W	GU75C	93-97	MCB 659 SV *	SRQ	CRQ		MCB 531 LF	SH
GT	1100			80-	MCB 501 *				MCB 73 LF	
GSF	1200	S, Bandit	GV75A	96-00	MCB 690 *	SV			MCB 531 LF	SH
GSF	1200	S, Bandit	WVA9	01-05	MCB 659 *	SV	SRQ	CRQ	MCB 531 LF	
GSF	1200	S, Bandit	WVCB	06	MCB 602 *	SV	SRQ	CRQ	MCB 634 LF	SH
GSX	1200	FS Inazuma	A3	99-01	MCB 683 *	SV	SRQ	CRQ	MCB 531 LF	SH
GSF	1250	ABS, S ABS	WVCH	07-	MCB 602 *	SV	SRQ	CRQ	MCB 634 LF	SH
GSX	1300	B-King, ABS	WVCR	07-	MCB 737 SV *	SRQ	CRQ		MCB 783 SH	SH
GSX	1300	R Hayabusa	A1	99-07	MCB 659 SV *	SRQ	CRQ		MCB 531 LF	SH
GSX	1300	R Hayabusa	WVCK	08-	MCB 752 SV *	SRQ	CRQ	SCR	MCB 783 SH	
GSX	1400		WVBN	01-07	MCB 659 *	SV	SRQ	CRQ	MCB 729 LF	
VS	1400	Intruder	VX51L/LD	87-	MCB 542				MCB 542 LF	
C	1500	Intruder		05-08	MCB 681	SV			MCB 741 LF	
C	1500	Intruder		05-08	MCB 682	SV				SH
M	1500	Intruder	WVCU	09-	MCB 681	SV			MCB 681	SH





→ **SUZUKI**

M	1500	Intruder	←	WVCU	09-	MCB 682	SV						
VL	1500	Intruder		WVAL	98-01	MCB 542					MCB 542 LF		
VL	1500	Intruder	→	WVAL	02-04	MCB 681	SV						
VL	1500	Intruder	←	WVAL	02-04	MCB 682	SV				MCB 741 LF	SH	
M	1600	Intruder	4	VNT60B	05-	MCB 742 SV					MCB 681	SH	
VZ	1600	Marauder			04-05	MCB 659	SV				MCB 681	SH	
M	1800	R, R2 Intruder		WVCA	06-	MCB 752 SV *					MCB 681	SH	
C	1800	R Intruder		WVCA	08-	MCB 776 SV *					MCB 681	SH	